

ENVIRONMENTAL AND SOCIAL IMPACT ASSESSMENT

AHAFO SOUTH PROJECT

Prepared by:

Newmont Ghana Gold Ltd.
C825/26 Lagos Avenue
East Legon, Accra, GHANA

Prepared for:

International Finance Corporation
2121 Pennsylvania Ave., NW, Room No. F-9K-198
Washington D.C 20433
USA

August 2005

TABLE OF CONTENTS

	<u>Page</u>
SUMMARY S-I	
CHAPTER 1 – INTRODUCTION	1-1
STRATEGIC JUSTIFICATION FOR THE PROJECT	1-1
PROJECT HISTORY	1-8
PROJECT DESCRIPTION	1-13
POLICY, LEGAL, AND ADMINISTRATIVE FRAMEWORK	1-14
General Institutional Framework	1-14
Regional Government	1-15
Local Government	1-16
Role of Traditional Authorities.....	1-17
General Legal Framework.....	1-17
Ghanaian Environmental and Occupational Health and Safety Regulations	1-19
International Agreements, Policies, and Standards	1-25
National Policies	1-29
Newmont Mining Corporation Policies.....	1-31
Requirements of Potential Investors, Lenders, and Insurers.....	1-40
CHAPTER 2 – PROJECT DESCRIPTION	2-1
INTRODUCTION	2-1
HISTORY OF MINING IN GHANA	2-2
PROJECT DESCRIPTION	2-5
Site Preparation	2-6
Mine Pits	2-6
Waste Rock Disposal Facilities	2-10
Tailing Storage Facility.....	2-11
Water Storage Facility	2-23
Surface Water Control Ditches	2-23
Environmental Control Dams	2-24
Process Plant	2-24
Roads	2-33
Concurrent Reclamation	2-34
Ancillary Facilities	2-34
EMPLOYMENT 2-37	
Recruitment.....	2-38
Training and Development.....	2-38
EXTERNAL AFFAIRS MANAGEMENT	2-39
ENVIRONMENTAL MANAGEMENT	2-43
Environmental Management Focus Areas	2-44
Environmental Control Measures	2-52
RECLAMATION AND CLOSURE PLAN	2-55
Mine Pits	2-56
Waste Rock Disposal Facilities	2-57

TABLE OF CONTENTS (continued)

	Page
Plant Site	2-57
Tailings Storage Facility	2-58
Water Storage Facility	2-58
Environmental Control Dams	2-58
Ancillary Facilities	2-59
Monitoring	2-59
Reclamation Costs	2-59
OCCUPATIONAL SAFETY AND HEALTH MEASURES	2-60
Training	2-61
Material Handling.....	2-62
Work Station Monitoring.....	2-63
Personal Protective Equipment.....	2-64
Quality Procedure Documentation	2-64

CHAPTER 3 – ALTERNATIVES

INTRODUCTION	3-1
Previous Environmental and Social Impact Analyses	3-1
Ongoing Environmental Studies.....	3-9
PROJECT ALTERNATIVES	3-10
No Project Alternative	3-10
Closure Alternatives.....	3-8

CHAPTER 4 – AFFECTED ENVIRONMENT AND HUMAN/ENVIRONMENTAL IMPACTS

INTRODUCTION	4-1
HUMAN ENVIRONMENT	4-5
Social and Economic Resources	4-5
Cultural Resources	4-45
Visual Quality	4-52
Noise and Vibration.....	4-54
BIOLOGICAL ENVIRONMENT	4-61
Biodiveristy	4-61
Flora	4-61
Fauna	4-62
Birds	4-73
Reptiles and Amphibians.....	4-74
Species of Conservation Concern	4-75
Wetlands	4-80
Aquatic Organisms.....	4-81
PHYSICAL ENVIRONMENT	4-84
Air Quality	4-84
Geology and Minerals.....	4-93
Surface Water Resources	4-105

TABLE OF CONTENTS (continued)

	<u>Page</u>
Groundwater Resources	4-127
Soil Resources	4-134
CUMULATIVE EFFECTS	4-150
Past and Present Activities.....	4-150
Reasonably Foreseeable Future Actions.....	4-150
Social and Economic Resources	4-158
Cultural Resources	4-158
Visual Resources.....	4-158
Noise and Vibration.....	4-159
Biodiversity-Forest Reserves.....	4-159
Flora	4-162
Fauna	4-162
Wetlands	4-163
Aquatic Organisms.....	4-163
Geology and Minerals.....	4-164
Water Resources	4-164
Soil Resources.....	4-164

CHAPTER 5 – ENVIRONMENTAL AND SOCIAL ACTION PLAN

INTRODUCTION	5-1
MANAGEMENT SYSTEMS	5-1
SOCIAL ACTION PLAN	5-2
Resettlement and Relocation of Local Communities	5-9
Local Infrastructure Pressures	5-12
Employment, Training, and Educational Opportunities.....	5-14
Local Economic Opportunities and Business Development.....	5-15
Community Health and Safety	5-18
On-Going Public Consultation and Disclosure	5-20
ENVIRONMENTAL ACTION PLAN	5-22
Environmental Management Programs.....	5-22
Environmental Monitoring Plans.....	5-32
Environmental Studies.....	5-35
Expanded Baseline Data Collection	5-35
OCCUPATIONAL HEALTH AND SAFETY ACTION PLAN	5-41
PROJECT INTEGRATION PLAN	5-44

TABLE OF CONTENTS (continued)

Page

LIST OF TABLES

TABLE S-1	Summary of Potential Impacts and Environmental Control Measures.....	S-4
TABLE I-1	Forest Reserve Condition Scores.....	1-22
TABLE I-2	Newmont's Five Star Performance and Evaluation Criteria.....	1-31
TABLE 2-1	Leading Gold Mines in Ghana in 2003.....	2-5
TABLE 2-2	Surface Disturbance by Mine Component.....	2-9
TABLE 2-3	Life-of-Mine Ore, Gold, and Waste Rock Production.....	2-10
TABLE 2-4	Environmental Control Dams.....	2-27
TABLE 2-5	Summary of Estimated Reclamation Costs.....	2-60
TABLE 2-6	Health and Safety Training Programs.....	2-62
TABLE 3-1	Alternative Mine Facility Locations Considered.....	3-5
TABLE 4-1	Total Ghanaian Labor Expenditures Ahafo South Project Construction Phase.....	4-14
TABLE 4-2	Land Use in Ahafo South Study Area.....	4-15
TABLE 4-3	Existing Potable Water Supply Facilities.....	4-19
TABLE 4-4	Existing sanitation Facilities and Status.....	4-20
TABLE 4-5	Estimated Royalty Schedule of Payments.....	4-32
TABLE 4-6	Sample of Potential Royalty Distribution Payments Year 2010.....	4-33
TABLE 4-7	Operations Staffing Level at Startup.....	4-34
TABLE 4-8	Total Ghanaian Labor Expenditures – Estimated Wage Distribution.....	4-38
TABLE 4-9	Star Ratings for Plant Species in Ghana.....	4-62
TABLE 4-10	Plant Species Occurrence by Star Rating in Ghana and Project Area.....	4-62
TABLE 4-11	Numbers of Vertebrate Species Relative to Forest Reserve.....	4-63
TABLE 4-12	Forest Reserve Condition Scores.....	4-64
TABLE 4-13	Large Mammals Documented in Project Area.....	4-72
TABLE 4-14	Bats Documented in Project Area.....	4-73
TABLE 4-15	Small Mammals Identified in Project Area.....	4-73
TABLE 4-16	Reptiles and Amphibians in Project Area.....	4-74
TABLE 4-17	Wildlife Ratings for Rarity and Human Demand.....	4-75
TABLE 4-18	Species with Conservation Status Documented for Project Area.....	4-76
TABLE 4-19	Fish Species Composition at Tano River Sample Sites.....	4-81
TABLE 4-20	Number of Benthic Invertebrate Species Recorded at Tano River Sample Stations....	4-83
TABLE 4-21	Density and Percent Compositions of Benthic Invertebrates Sampled in Tano River	4-83
TABLE 4-22	Mine Operating Statistics.....	4-85
TABLE 4-23	Annual PM ₁₀ Fugitive Emissions Summary for Ahafo South Mine.....	4-86
TABLE 4-24	Results of Static Acid-Base Accounting Tests.....	4-100
TABLE 4-25	Statistical Comparison of Net Carbonate Value of Ahafo Ore and Waste Rock.....	4-103
TABLE 4-26	Average Composition of Oxide and Sulfide Zone Mineralogy.....	4-104
TABLE 4-27	Whole Rock Data for Apensu Mine Pit Area Compared to Average Crustal Values.....	4-105
TABLE 4-28	Mean Monthly Flow Measured for Tano River at Hwidiem (1969-1996).....	4-111

TABLE OF CONTENTS (continued)

	<u>Page</u>
TABLE 4-29 Mean Monthly Flow Calculated for Subri Watershed	4-112
TABLE 4-30 Annual Runoff Calculated Into Water Storage Facility.....	4-113
TABLE 4-31 Mean Monthly Flow Calculated for Water Storage Facility	4-113
TABLE 4-32 Peak Flood Flows Calculated for Water Storage Facility.....	4-113
TABLE 4-33 Mean Monthly Flow Calculated for Awonsu Sub-Basin.....	4-114
TABLE 4-34 Peak Flood Flows Calculated for Awonsu Sub-Basin.....	4-114
TABLE 4-35 Surface Water Monitoring Locations.....	4-115
TABLE 4-36 Water Quality Standards and Guideline Values.....	4-117
TABLE 4-37 Summary of Surface Water Quality	4-118
TABLE 4-38 Analysis of Pregnant Solution after Leaching Ore	4-125
TABLE 4-39 Groundwater Monitoring Locations	4-129
TABLE 4-40 Summary of Groundwater Quality.....	4-131
TABLE 4-41 Topsoil Depth by Series.....	4-145
TABLE 4-42 Estimated Topsoil Salvage Area and Volume.....	4-145
TABLE 4-43 Volter River Authority Proposed Utility Corridor	4-153
TABLE 5-1 Summary of Potential Impacts to the Human Environment, Mitigation Measures, and Additional Actions Required	5-3
TABLE 5-2 Social Action Plan.....	5-6
TABLE 5-3 Summary of Potential Impacts and Environmental Monitoring and Control Measures	5-23
TABLE 5-4 Environmental Action Plan.....	5-28
TABLE 5-5 Occupational Health and Safety Action Plan	5-40

LIST OF FIGURES

FIGURE S-1 General Location Map.....	S-3
FIGURE S-2 Lease Areas.....	S-17
FIGURE 1-1 General Location Map	1-3
FIGURE 1-2 Newmont Ghana Gold, Ltd. Ownership Structure.....	1-5
FIGURE 1-3 Lease Areas	1-9
FIGURE 1-4 Ghanaian EPA Guidelines for Approval Process	1-11
FIGURE 2-1 Gold Mining Operations in Ghana.....	2-3
FIGURE 2-2 Mine and Facility Site Plan.....	2-7
FIGURE 2-3 Tailing Underdrain Layout	2-13
FIGURE 2-4 South Embankment Section	2-17
FIGURE 2-5 Underdrain Sections.....	2-21
FIGURE 2-6 Process Flow Diagram.....	2-25
FIGURE 2-7 Carbon-in-Leach Circuit	2-29
FIGURE 2-8 Organizational Chart for External Affairs.....	2-41
FIGURE 2-9 Environmental Management Structure.....	2-45

TABLE OF CONTENTS (continued)

	<u>Page</u>
FIGURE 3-1 Alternative Tailing and Water Storage Facility Sites	3-7
FIGURE 4-1 Project/Study Area	4-3
FIGURE 4-2 Cultural Sites	4-47
FIGURE 4-3 View-Point Locations	4-55
FIGURE 4-4 Isopleths of 24-Hour PM ₁₀ Concentrations	4-89
FIGURE 4-5 Isopleths of Annual Average PM ₁₀ Concentrations	4-91
FIGURE 4-6 Geology of Southwest Ghana.....	4-95
FIGURE 4-7 Surface Water Monitoring Sites	4-107
FIGURE 4-8 Soil Map	4-137
FIGURE 4-9 Proposed Volta River Authority Transmission Line.....	4-151

LIST OF APPENDICES

- APPENDIX A Malaria and HIV/AIDS Policies
- APPENDIX B Bird Species
- APPENDIX C Surface Water Quality
- APPENDIX D Groundwater Quality
- APPENDIX E Public Consultation and Disclosure Plan
- APPENDIX F List of Preparers
- APPENDIX G References